



CONDITION REPORT

2024 BMW 330e xDrive Touring (G21) 330e xDrive Touring (G21) 215HP

2024 | 17142 KM | auto | Petrol | 215 kw


Seller Disclosure



7188MSX

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	M Portimao Blue metallic
HP	215 kw
VIN	WBA71CY090FT57589
Technical Inspection	
DUA	No
Registration Date	11-07-2024
Last Service Date	-

- 2^e CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/7188MSX.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Location

Auction Centre

-

Madrid

Inspection

Location

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -