



CONDITION REPORT

2020 Jaguar E-PACE 2 E-PACE 2.0D 110kW HP

2020 | 123823 KM | Manual | DIESELMOTOR |

Seller Disclosure



3253LGC

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	-
HP	-
VIN	SADFB2DN1L1Z82937
Technical Inspection	
DUA	No
Registration Date	09-03-2020
Last Service Date	-



2^a CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN (Informe Técnico) PARA COMPROBAR POSIBLES DAÑOS E INFORMACIÓN ADICIONAL


Location
Auction Centre

Madrid
Madrid


Inspection

Location Madrid
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -