



# CONDITION REPORT

2020 BMW BMW i3 (I01) BMW i3 (I01) 125HP

2020 | 31933 KM | auto | electric | 125 kw

Seller Disclosure



**8585LJW**

|                      |                                     |
|----------------------|-------------------------------------|
| Engine Size          | -                                   |
| Seats                | -                                   |
| Number of Doors      | -                                   |
| Body Style           | -                                   |
| Body Colour          | Mineralgrau con detalles BMW i Blau |
| HP                   | 125 kw                              |
| VIN                  | WBY8P210107F13582                   |
| Technical Inspection |                                     |
| DUA                  | No                                  |
| Registration Date    | 17-09-2020                          |
| Last Service Date    | -                                   |



2ª CHAVE



ONDERHOUDSBOEKJE



VAT












Sold as Seen



| Equipment | Public Notes                                                                                                                                                   | Inspection                                    |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
|           | DOCUMENTACION EN CUSTODIA DE GESTORIA<BR><a href="http://soportemanheim.es/E/8585LJW.htm" target="_blank">CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO</a><br> | <div>Location-<br/>Auction CentreMadrid</div> |

| Inspection                                    |
|-----------------------------------------------|
| <div>Location-<br/>Auction CentreMadrid</div> |

Damage Assesment

|                                                                                     |                                                                                     |                                                                                     |                                                                                      |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
|    |    |   |   |
| Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                              |
|   |   |  |  |
| Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                              |
|  |  |                                                                                     |                                                                                      |
| Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             | Damage Detail : -<br>Damage Type : -<br>Damage Size : -                             |                                                                                     |                                                                                      |