



CONDITION REPORT

2020 BMW X6 xDrive30d (G06) X6 xDrive30d (G06) 210HP

2020 | 113728 KM | auto | DIESELMOTOR | 210 kw

Seller Disclosure



7365LKK

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Manhattan metalizado
HP	210 kw
VIN	WBAGT810909D94919
Technical Inspection	
DUA	No
Registration Date	16-10-2020
Last Service Date	-



2ª CHAVE



ONDERHOUDSBOEKJE



VAT




Sold as Seen




Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -