



CONDITION REPORT

2019 BMW X7 xDrive40i 340HP

2019 | 1 KM | auto | Petrol | 340 hp


Seller Disclosure



7710KWZ

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Carbonschwarz
HP	340 hp
VIN	WBACW21060LS05209
Technical Inspection	
DUA	No
Registration Date	16-05-2019
Last Service Date	-

-  2^a CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment

Public Notes

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Inspection

Location Madrid
Auction Centre Madrid

Inspection

Location Madrid
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -