



# CONDITION REPORT

2019 Peugeot Rifter Access Standard BlueHDi 73kW 100HP

2019 | 1 KM | Manual | DIESELMOTOR | 100 hp


Seller Disclosure



**5639LBW**

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco banquise
HP	100 hp
VIN	VR3ECYHYCKJ646612
<b>Technical Inspection</b>	
DUA	No
Registration Date	17-10-2019
Last Service Date	-

- 2<sup>a</sup> CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



### Equipment

---

### Public Notes

---

IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

### Inspection

---

**Location** Madrid  
**Auction Centre** Madrid

### Inspection

---

**Location** Madrid  
**Auction Centre** Madrid

### Damage Assesment

---



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -