



# CONDITION REPORT

**2019 BMW X5 xDrive45e 394HP**


2019 | 109710 KM | auto | hybrid | 394 hp

Seller Disclosure



**4777LDN**

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Arktikgrau
HP	394 hp
VIN	WBATA610209B18848
<b>Technical Inspection</b>	
DUA	No
Registration Date	27-12-2019
Last Service Date	-

-  2<sup>a</sup> CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



### Equipment

### Public Notes

IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

### Inspection

<b>Location</b>	Madrid
<b>Auction Centre</b>	Madrid

### Inspection

<b>Location</b>	Madrid
<b>Auction Centre</b>	Madrid

### Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -