



CONDITION REPORT

2021 Mazda CX-5 CX-5 (O)2.2 D 110KW ZENITH SAFETY 2WD
150HP

2021 | 116517 KM | Manual | DIESELMOTOR | 150 hp

Seller Disclosure

0092LNB

Engine Size	2191 cm3
Seats	-
Number of Doors	5
Body Style	-
Body Colour	METALIZADA
HP	150 hp
VIN	JMZKF6W1690121697
Technical Inspection	
DUA	No
Registration Date	10-03-2021
Last Service Date	-

- ✗ 2º CHAVE
- ✗ ONDERHOUDSBOEKJE
- ✓ VAT
- ✗ Sold as Seen



Equipment

Public Notes

Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Location
Auction Centre


-
Madrid

Inspection

Location
Auction Centre

-
Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -