



CONDITION REPORT

2021 BMW 118d (F40) 118d (F40) 110HP

2021 | 66485 KM | auto | DIESELMOTOR | 110 kw

Seller Disclosure



6801LVP

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	110 kw
VIN	WBA7M910607K46495
Technical Inspection	
DUA	No
Registration Date	28-12-2021
Last Service Date	-



2^a CHAVE



ONDERHOUDSBOEKJE



VAT














Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment

 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -
 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -	 Damage Detail : - Damage Type : - Damage Size : -