



CONDITION REPORT

2022 BMW 118d (F40) 118d (F40) 110HP

2022 | 92409 KM | auto | DIESELMOTOR | 110 kw

Seller Disclosure



9215LWL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Skyscraper Grau metalizado
HP	110 kw
VIN	WBA7M910607K59151
Technical Inspection	
DUA	No
Registration Date	22-02-2022
Last Service Date	-



2^a CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

DOCUMENTACION EN CUSTODIA DE
GESTORIA
<a
href="http://soportemanheim.es/E/9215LWL.htm"
target="_blank">CLICK AQUÍ PARA VER
EL EQUIPAMIENTO
COMPLETO

Location

Auction Centre

-

Madrid

Inspection

Location

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -