



## CONDITION REPORT

2020 HYUNDAI TUCSON TUCSON 1.6 CRDI 100KW 48V  
STYLE DT 2WD 136HP

2020 | 92938 KM | Manual | | 136 hp

Seller Disclosure

9268LGK

|                      |                   |
|----------------------|-------------------|
| Engine Size          | 1598 cm3          |
| Seats                | -                 |
| Number of Doors      | 5                 |
| Body Style           | -                 |
| Body Colour          | POLAR WHITE       |
| HP                   | 136 hp            |
| VIN                  | TMAJ3817GLJ044804 |
| Technical Inspection |                   |
| DUA                  | No                |
| Registration Date    | 22-05-2020        |
| Last Service Date    | -                 |

- ☒ 2º CHAVE
- ☒ ONDERHOUDSBOEKJE
- ☒ VAT
- ☒ Sold as Seen



### Equipment

### Public Notes

### Inspection

<https://www.manheimtransportatucoche.es/es/transportes/manheim> CALCULA TU TRANSPORTE

Location  
Auction Centre

### Inspection

Location  
Auction Centre

-  
Madrid

## Damage Assesment

---



Damage Detail : -

Damage Type : -

Damage Size : -