



CONDITION REPORT

2019 BMW i BMW i3 (I01) BMW i3 (I01) 125HP

2019 | 102617 KM | auto | electric | 125 kw

Seller Disclosure



0267KYN

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Fluid Black con detalles BMW i Blau
HP	125 kw
VIN	WBY8P210707E07749
Technical Inspection	
DUA	No
Registration Date	28-06-2019
Last Service Date	-



2ª CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment
 Damage Detail : - Damage Type : - Damage Size : -  Damage Detail : - Damage Type : - Damage Size : -