



# CONDITION REPORT

2024 BMW 118d (F40) 118d (F40) 110HP  
2024 | 19485 KM | auto | DIESELMOTOR | 110 kw  
Seller Disclosure



8796MPB


|                                                                                                           |                   |
|-----------------------------------------------------------------------------------------------------------|-------------------|
| Engine Size                                                                                               | -                 |
| Seats                                                                                                     | -                 |
| Number of Doors                                                                                           | -                 |
| Body Style                                                                                                | -                 |
| Body Colour                                                                                               | black             |
| HP                                                                                                        | 110 kw            |
| VIN                                                                                                       | WBA7M910X07P23221 |
| Technical Inspection                                                                                      |                   |
| DUA                                                                                                       | No                |
| Registration Date                                                                                         | 19-03-2024        |
| Last Service Date                                                                                         | -                 |
|  2 <sup>e</sup> CHAVE |                   |
|  ONDERHOUDSBOEKJE    |                   |
|  VAT                 |                   |
|  Sold as Seen        |                   |




| Equipment | Public Notes                                                                                                                                                   | Inspection                                    |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|
|           | DOCUMENTACION EN CUSTODIA DE GESTORIA<BR><a href="http://soportemanheim.es/E/8796MPB.htm" target="_blank">CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO</a><br> | <div>Location-<br/>Auction CentreMadrid</div> |

| Inspection                                    |
|-----------------------------------------------|
| <div>Location-<br/>Auction CentreMadrid</div> |


Damage Assesment




Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -



Damage Detail : -  
Damage Type : -  
Damage Size : -