



CONDITION REPORT

2022 BMW 116d (F40) 116d (F40) 85HP

2022 | 66381 KM | auto | DIESELMOTOR | 85 kw

Seller Disclosure



7727LWL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Mineralweiss metalizado
HP	85 kw
VIN	WBA7M710207K65971
Technical Inspection	
DUA	No
Registration Date	22-02-2022
Last Service Date	-



2ª CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

LocationSevilla-ES50


Auction CentreMadrid

Inspection

LocationSevilla-ES50

Auction CentreMadrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -