



CONDITION REPORT

2021 DS DS 7 CROSSBACK 1.6 E-Tense 225 PERFORMANCE
LINE Auto 225HP

2021 | 45291 KM | auto | hybrid | 225 hp

Seller Disclosure



0723LVL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Cristal pearl
HP	225 hp
VIN	VR1J4DGZUMY540559
Technical Inspection	
DUA	No
Registration Date	20-12-2021
Last Service Date	-



2^e CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -