



CONDITION REPORT

2021 DS DS 3 CROSSBACK PureTech 73 kW Manual
PERFORMANCE LINE 100HP

2021 | 63301 KM | Manual | Petrol | 100 hp

Seller Disclosure



5406LVR

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco banquise
HP	100 hp
VIN	VR1URHNEKMW098310
Technical Inspection	
DUA	No
Registration Date	28-12-2021
Last Service Date	-
2 ^a CHAVE	
ONDERHOUDSBOEKJE	
VAT	
Sold as Seen	



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -