



CONDITION REPORT

2022 BMW 118d (F40) 118d (F40) 110HP

2022 | 65514 KM | auto | DIESELMOTOR | 110 kw


Seller Disclosure



1940LWB

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	white
HP	110 kw
VIN	WBA7M910607K36002
Technical Inspection	
DUA	No
Registration Date	26-01-2022
Last Service Date	-

-  2^e CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -