



CONDITION REPORT

2019 Peugeot Rifter Access Standard BlueHDi 73kW 100HP

2019 | 127103 KM | Manual | DIESELMOTOR | 100 hp

Seller Disclosure



5862LBX

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco
HP	100 hp
VIN	VR3ECYHYCKJ756673

Technical Inspection

DUA	No
Registration Date	21-10-2019
Last Service Date	-

-  2ª CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid


Inspection

Location -
Auction Centre Madrid


Damage Assesment




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -