



CONDITION REPORT

2024 BMW 116d (F40) 116d (F40) 85HP
2024 | 10255 KM | Manual | DIESELMOTOR | 85 kw
Seller Disclosure



0293MMV

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	-
HP	85 kw
VIN	WBA7M710407N51000
Technical Inspection	
DUA	No
Registration Date	18-01-2024
Last Service Date	-

-  2^e CHAVE
-  ONDERHOUDSBOEKJE
-  VAT
-  Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Location

Auction Centre

-

Madrid

Inspection


Location

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -

Damage Type : -

Damage Size : -