



CONDITION REPORT

2022 BMW 318d Berlina (G20) 318d Berlina (G20) 110HP

2022 | 120107 KM | auto | DIESELMOTOR | 110 kw

Seller Disclosure



5133LZD

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	-
HP	110 kw
VIN	WBA5V310X0FN15654
Technical Inspection	
DUA	No
Registration Date	12-07-2022
Last Service Date	-

- 2^a CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

POSIBILIDAD EXTRAVIO FT
CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO

Location

Auction Centre

-

Madrid

Inspection

Location

Auction Centre

-

Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -