



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 94791 KM | auto | DIESELMOTOR | 85 kw

Seller Disclosure



4886LNB

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710505T32283
Technical Inspection	
DUA	No
Registration Date	11-03-2021
Last Service Date	-



2^a CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -




Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -



Damage Detail : -
Damage Type : -
Damage Size : -