



CONDITION REPORT

2021 BMW 116d (F40) 116d (F40) 85HP

2021 | 89125 KM | Manual | DIESELMOTOR | 85 kw

Seller Disclosure



5817LNS

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	grey
HP	85 kw
VIN	WBA7M710305T28233
Technical Inspection	
DUA	No
Registration Date	14-04-2021
Last Service Date	-

- 2^e CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment	Public Notes	Inspection
	DOCUMENTACION EN CUSTODIA DE GESTORIA CLICK AQUÍ PARA VER EL EQUIPAMIENTO COMPLETO 	Location- Auction CentreMadrid

Inspection
Location- Auction CentreMadrid

Damage Assesment
 Damage Detail :- Damage Type :- Damage Size :-  Damage Detail :- Damage Type :- Damage Size :-