



# CONDITION REPORT

2022 BMW SERIE 1 118d HP

2022 | 45465 KM | | DIESELMOTOR |


Seller Disclosure



1462LYR

|                      |            |
|----------------------|------------|
| Engine Size          | -          |
| Seats                | -          |
| Number of Doors      | -          |
| Body Style           | -          |
| Body Colour          | -          |
| HP                   | -          |
| VIN                  | -          |
| Technical Inspection |            |
| DUA                  | No         |
| Registration Date    | 17-06-2022 |
| Last Service Date    | -          |

- 2<sup>a</sup> CHAVE
- ONDERHOUDSBOEKJE
- VAT
- Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN  
(Informe Tecnico) PARA COMPROBAR  
POSIBLES DAÑOS E INFORMACIÓN  
ADICIONAL

|                |          |
|----------------|----------|
| Location       | Mallorca |
| Auction Centre | Madrid   |

Inspection

|                |          |
|----------------|----------|
| Location       | Mallorca |
| Auction Centre | Madrid   |

Damage Assesment



Damage Detail : -  
Damage Type : -  
Damage Size : -