



CONDITION REPORT

2021 Peugeot 3008 1.5 BlueHDi 96kW (130CV) S&S Allure Pack 130HP

2021 | 107413 KM | Manual | DIESELMOTOR | 130 hp

Seller Disclosure



5347LVL

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco nacarado (3 c
HP	130 hp
VIN	VF3MCYHZMMS248163
Technical Inspection	
DUA	No
Registration Date	21-12-2021
Last Service Date	-



2º CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -