



CONDITION REPORT

2021 MERCEDES Vito 111 CDI Larga 114HP

2021 | 137329 KM | Manual | DIESELMOTOR | 114 hp

Seller Disclosure



3816LMP

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco artico
HP	114 hp
VIN	WDF44760313617332
Technical Inspection	
DUA	No
Registration Date	16-02-2021
Last Service Date	-



2ª CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection

IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -