



CONDITION REPORT

2022 DS DS 3 CROSSBACK PureTech 73 kW Manual
PERFORMANCE LINE 100HP

2022 | 91841 KM | Manual | | 100 hp

Seller Disclosure



4583LWP

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco banquise
HP	100 hp
VIN	VR1URHNEKMW108879
Technical Inspection	
DUA	No
Registration Date	28-02-2022
Last Service Date	-



2^e CHAVE




ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

IMPORTANTE: VER PERITACIÓN
(Informe Técnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL


Inspection

Location	-
Auction Centre	Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -