



CONDITION REPORT

2019 Citroen C3 BlueHDi 73KW (100CV) S&S FEEL 99HP

2019 | 66133 KM | Manual | DIESELMOTOR | 99 hp

Seller Disclosure



7229KWV

Engine Size	-
Seats	-
Number of Doors	-
Body Style	-
Body Colour	Blanco
HP	99 hp
VIN	VF7SXYHYPKT586918
Technical Inspection	
DUA	No
Registration Date	07-05-2019
Last Service Date	-



2ª CHAVE




ONDERHOUDSBOEKJE



VAT



Sold as Seen



Equipment

Public Notes

Inspection


IMPORTANTE: VER PERITACIÓN
(Informe Tecnico) PARA COMPROBAR
POSIBLES DAÑOS E INFORMACIÓN
ADICIONAL

Location -
Auction Centre Madrid

Inspection

Location -
Auction Centre Madrid

Damage Assesment



Damage Detail : -
Damage Type : -
Damage Size : -