



CONDITION REPORT

BMW Serie-1 LCI Diesel 116 d EfficientDynamics 116HP
Hatchback
| 182911 KM | Manual | DIESELMOTOR | 116 hp

4 **Grade**
Manheim



86-QX-25

Engine Size	1496 cm3
Seats	5
Number of Doors	5
Body Style	Hatchback
Body Colour	Branco
HP	116 hp
VIN	WBA1V91080V735723
Technical Inspection	
DUA	Yes
Registration Date	
Last Service Date	REGISTO DIGITAL

- ✓ 2ª CHAVE
- ✓ ONDERHOUDSBOEKJE
- ✗ VAT
- ✗ Sold as Seen



Condition Info

Sold as Seen	No
MOTOR	-
Transmission	-
Suspension	-
Brakes	-
Clutch	-
Gearbox	-
Steering	-

Equipment

PARKEERHULP
LICHTMETALEN VELGEN
CAIXA 6
AC AUTOMATICO
LED DIURNOS PRESENÇA
XENON LAMPEN
LIVRO DE REVISOES DIGITAL
SECOND KEYS

Public Notes

REGISTO DIGITAL
CUSTO AVERB 108€/
DEMORA APROX 60 DIAS
SEM DUA E IPO DISPONIVEIS NA
MANHEIM

Inspection

Location	Lisboa
Auction Centre	Lisboa

Damage Assesment



Damage Detail : Pára-choques_frente
Damage Type : Danificado
Damage Size : Ver Imagem



Damage Detail : Pára-choques_traseiro
Damage Type : Raspado
Damage Size : Ver Imagem



Damage Detail : Habitáculo
Damage Type : C/ desgaste
Damage Size : Ver Imagem



Damage Detail : Habitáculo
Damage Type : Buraco resultante de
queimadura
Damage Size : Ver Imagem



Damage Detail : Habitáculo
Damage Type : C/ desgaste
Damage Size : Ver Imagem