



CONDITION REPORT

2019 Renault Clio V Diesel 1.5 Blue dCi RS Line 115HP
Hatchback

2019 | 62004 KM | Manual | DIESELMOTOR | 115 hp

3

Grade
Manheim

45-ZQ-70

Engine Size	1461 cm3
Seats	5
Number of Doors	5
Body Style	Hatchback
Body Colour	Cinzent
HP	115 hp
VIN	
Technical Inspection	
DUA	Yes
Registration Date	23-12-2019
Last Service Date	AOS 11188 KMS EM 08.02.2021



2^a CHAVE



ONDERHOUDSBOEKJE



VAT



Sold as Seen



MANHEIM
Auction Services
COX AUTOMOTIVE



Condition Info

Sold as Seen	No
MOTOR	Good
Transmission	Good
Suspension	Good
Brakes	Good
Clutch	Good
Gearbox	Good
Steering	Good

Equipment

GPS
LICHTMETALEN VELGEN
PARKEERHULP
AC AUTOMÁTICO
ONDERHOUDSBOEKJE

Public Notes

DOCUMENTACAO
CUSTO AVERBAMENTO 108€
APROXIMADAMENTE 45 DIAS

Inspection

Location	Lisboa
Auction Centre	Lisboa

Damage Assesment



Damage Detail : Pára-choques_frente
Damage Type : Raspado
Damage Size : Ver Imagem



Damage Detail : Pára-brisas_frente
Damage Type : Picado
Damage Size : Ver Imagem



Damage Detail : Porta_frente_esquerda
Damage Type : Riscos
Damage Size : Ver Imagem



Damage Detail : Porta_detrás_direita
Damage Type : Riscos
Damage Size : Ver Imagem



Damage Detail : Volante
Damage Type : Sujo
Damage Size : Ver Imagem



Damage Detail : Banco_Condutor
Damage Type : Sujo
Damage Size : Ver Imagem